Sanitized Copy Approved for Release 2011/07/20: CIA-RDP61-00763A000200110109-1

SECRET

NPD 7361-59 2 November 1959

MEMORANDAN FOE: Chief, Material Branch, DPD-DD/P

SUBJECT

: Malfunction Report for October 1959

25X1

1. reported the following ELIEF equipment malfunctions for the period:

A. System III

- (1) Mission 315, 6 October Lost D.C. Power about two-thirds of the way through the mission. Cause undetermined.
- (2) Mission 1525, 9 October Planar triode tube in BRB presmp failed, reducing the System III sensitivity.
- (3) Mission 86k9, 30 October The 05 Board of the third local oscillator, Receiver "A", failed at the start of the mission. Cause unknown.
- (4) Mission S649, 30 October Recorder 780 failed after 64 hours. Cause unknown. Operated properly on post flight check.

B. System VII

(1) Mission 4139, 4 October - Intermittent in 10db alternator pad. Replaced.

2. The report from will be delayed.

25X1

Chief, Communications Section DFD-DD/P

25X1

Metributions

Orig & 1 - Addressee

1 - 0-15

LA RI

1 - Chrono

WWB/bs

اللها اللها